Annexure D

BUILDING SAFETY CERTIFICATE

No60	22.00.20
110	Dated: - 25°

It is certified that the existing building Shri Guru Nanak Dev Public School at Vill. & Post – Bansi Pargana-Bhood Tehsil- Gola Gokarannath Distt. -Lakhimpur- Kheri (UP) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1) (School Building)	Block (2) (Office Block)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	Ground + 01	NA	NA	NA	NA	NA

The building is owned/occupied by Shri Guru Nanak Dev Public School have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Rural Engineering Department on 23.06.2025 in the presence of Mr. Devendra Singh S/O Mr. Manjeet Singh, Vill. & Post — Bansi Pargana-Bhood Tehsil- Gola Gokarannath Distt. - Lakhimpur- Kheri (UP) and that the building/premises is fit for occupancy for running school with effect from 23.06.2025 for a period of Five Years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1- If intensity of earthquake in this region occurs more than 06.00 on reactor scale this certificate become invalid, inspection of building should be done again.
- 2- If No's of floor is increased then this certificate becomes invalid.
- 3- Proper maintenance should be done as per building by-laws and the national building code by the organization.

Issued on 24.66.25 at dakhimeux by	
------------------------------------	--

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal :_____

Name:

Designation :

ग्रामीण अभियन्त्रण

Name & Address of Department of the Color

सेवा में.

मुख्य विकास अधिकारी, लखीमपुर खीरी।

पत्रांक ८० / ग्रा०अ०वि० / २०२५ / दिनॉक:- २३:०६ • २०२ ४

महोदय,

आपके कार्यालय पत्रांक 2418—19/एस0टी0/2025—26 दिनॉक—18.06.2025 के क्रम में श्री गुरु नानक देव पब्लिक स्कूल ग्राम—बांसी, परगना—भूड़ तहसील—गोला गोकरन नाथ जिला—लखीमपुर खीरी का नेशनल बिल्डिंग कोड के संबंध में दिनॉक 23.06.2025 को निरीक्षण किया गया। निरीक्षण के समय विद्यालय का निर्माण हुआ पाया गया। प्रथम दृष्ट्या विद्यालय की छत एवं दीवारों की गुणवत्ता संतोषजनक पायी गयी। कक्षा—कक्ष में खिडिकियों की पर्याप्त व्यवस्था है, तथा वे हवादार एवं रोशनी युक्त है। विद्यालय भवन में ठण्ड एवं धूप की पर्याप्त व्यवस्था की गयी है। शुलभ संदर्भ हेतु प्रमाण पत्र एवं विद्यालय के कमरे, दरवाजे एवं खिडिकी का विवरण संलग्न कर प्रेषित है।

भवदीय

Digitally signed by RAVI SHANKER SRIVASTAVA Date: 23-06-2025 20:37:03

सहायक अभियन्ता ग्रामीण अभियन्त्रण विभाग, लखीमपुर खीरी।

संलग्नक- उपरोक्तानुसार।

1- आवेदन पत्र मूलरूप में।

2- प्रमाण-पत्र।

3- कमरो का विवरण ।

4- चेक लिस्ट।